


3. External dimensions and weight

Unit: mm


(1) 20/30A



Weight: Approx. 1.7 kg


Note: Do not use M4 screws without square washers.

(2) 50/75A



Weight: Approx. 3.3 kg

(3) 100A



Weight: Approx. 3.8 kg

Unit: mm